PRINTED: 07/08/2013 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION  A DULL DOLG  01			(X3) DATE SURVEY COMPLETED	
15G279		15G279	A. BUILDING B. WING			06/24/2013		
NAME OF PROVIDER OR SUPPLIER			•	227 E H				
JAY-RAN	IDOLPH DEVELOP	MENTAL SERVICES		PORTL	AND, IN 47371			
(X4) ID PREFIX	SUMMARY STATEMENT OF DEFICIENCIES			ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD B			(X5) COMPLETION	
TAG	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			TAG	CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		DATE	
K010000								
	A Life Safety Code Recertification Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j).		K0:	10000				
	Survey Date: 06/24/13							
	Facility Number	: 000799						
	Provider Number: 15G279							
	AIM Number: 100249030							
	Surveyor: Mark Specialist	Bugni, Life Safety Code						
	was found not in Requirements fo Medicaid, 42 CF Life Safety from of the National F Association (NF Code (LSC), Cha Residential Boar	evelopmental Services compliance with r Participation in R Subpart 483.470(j), Fire and the 2000 edition Fire Protection PA) 101, Life Safety apter 33, Existing d and Care Occupancies.						
	was not sprinkled fire alarm system on all levels included common living a smoke detection	ncility with a basement red. The facility has a must smoke detection uding in the corridors, in areas, and single station in all client sleeping lity has a capacity of 7						

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any defiency statement ending with an asterisk (\*) denotes a deficency which the institution may be excused from correcting providing it is determined that other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Facility ID:

## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/08/2013 FORM APPROVED OMB NO. 0938-0391

AND PLAN OF CORRECTION		IDENTIFICATION NUMBER:  15G279	A. BUILDING  B. WING		COMPLETED 06/24/2013		
NAME OF PROVIDER OR SUPPLIER  JAY-RANDOLPH DEVELOPMENTAL SERVICES			STREET ADDRESS, CITY, STATE, ZIP CODE  227 E HIGH ST PORTLAND, IN 47371				
	SUMMARY ST (EACH DEFICIENCE REGULATORY OR and had a census survey. Calculation of th Score (E-Score) Alternative Appr Chapter 6, rated an E-Score of 0.7 Quality Review I Safety Code Specon 06/25/13. The facility was	MENTAL SERVICES  TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION) of 7 at the time of this  The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty using NFPA 101A, toaches to Life Safety, the facility Prompt with The Evacuation Difficulty the Evacuation Diffic		G STREET A 227 E H	IIGH ST		(X5) COMPLETION DATE

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 7S3J21

Facility ID: 000799

If continuation sheet Page 2 of 4

PRINTED: 07/08/2013 FORM APPROVED OMB NO. 0938-0391

	TOF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA  IDENTIFICATION NUMBER:  15G279	(X2) MULTIPLE CO A. BUILDING	ONSTRUCTION 01	(X3) DATE SURVEY COMPLETED 06/24/2013		
	156219	B. WING		00/24/2013		
NAME OF PROVIDER OR SUPPLIER  JAY-RANDOLPH DEVELOPMENTAL SERVICES		STREET ADDRESS, CITY, STATE, ZIP CODE  227 E HIGH ST PORTLAND, IN 47371				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE		
K01S041	483.470(j)(1)(i) LIFE SAFETY CODE STANDARD Every sleeping room and living area has access to a primary means of escape located to provide a safe path of travel to the outside. 33.2.2.2.1.  Where sleeping rooms or living areas are above or below the level of exit discharge, the primary means of escape is an interior stair in accordance with 32.2.2.4 and 33.2.2.4, an exterior stair, a horizontal exit, or a fire escape stair. 32.2.2.2.  Based on observation and interview, the facility failed to ensure 1 of 3 means of egress was continuously maintained for full instant use in case of fire or other emergencies for 2 of 8 clients. LSC 33.2.2.6.1 requires stairs to comply with 7.2.2. 7.2.2 requires stairs used as a component in the means of egress shall conform to the general requirements of Section 7.1 and to the special requirements of this subsection. 7.1.10.1 requires means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergencies. This deficient practice affects all clients in the facility who would use the first floor West exit during an evacuation.  Findings include:  Based on observation on 06/24/13 at	K01S041	Now and in the future, all mea of egress will be continuously maintained for instant use in coffire or other emergencies. Home Manager will report any obstructions to safe egress immediately to the Residentia Department Head, who is responsible for securing maintenance of the structure.	case		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 7S3J21

Facility ID: 000799

If continuation sheet

Page 3 of 4

## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/08/2013
FORM APPROVED
OMB NO. 0938-0391

		IDENTIFICATION NUMBER:  15G279	A. BUILDING B. WING	01	COMPLETED 06/24/2013			
NAME OF PROVIDER OR SUPPLIER  JAY-RANDOLPH DEVELOPMENTAL SERVICES			STREET ADDRESS, CITY, STATE, ZIP CODE  227 E HIGH ST PORTLAND, IN 47371					
(X4) ID PREFIX TAG	(EACH DEFICIEN	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	(X5) COMPLETION DATE			
	manager, the first exterior concrete broken in the cer Furthermore, the broken concrete with broken piece ground surface.	the assistant home t floor West exit had an e stairway which was nter of the bottom stair. entire bottom stair had along the top of the stair es of concrete on the This was verified by the nanager at the time of						

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 7S3J21

Facility ID: 000799

If continuation sheet

Page 4 of 4